PH-C350ap_BK01


PACKAGE CONTENTS Socket Screws for: Thermal Compound - AM4 (PH-NDC_01) **Acetal Standoff** C350ap Block

DISCLAIMER - This product is intended for advanced users. Please consult with a qualified technician for installation. Phanteks assumes no liability for any damages occurring as a result of using Phanteks cooling products.

WARNING - Power down the system before installation.


- Do not disassemble the waterblock. Warranty will be voided.
- Perform a leak test before turning on the system.
- Check our website for the latest installation guide.

INSTALLATION for socket AM4




STEP 1. REMOVE THE ORIGINAL PLASTIC CLAMPS

Use a Philips-head screwdriver to remove the four (4) screws (in red). Remove the plastic clamps from the motherboard and make sure the original AMD backplate stays in place.




STEP 2. INSTALLING THE SOCKET SCREWS

Place and tighten the four (4) included socket screws by hand on the AM4 socket.




STEP 3. INSTALLING THE ACETAL STANDOFFS

Place the four (4) included Acetal Standoffs onto the socket screws.



STEP 4. APPLYING THERMAL COMPOUND

Make sure the CPU is clean and clear of any residual traces of thermal paste. Apply a dot (4-5mm size) of Phanteks thermal compound on the center of the CPU surface.





STEP 5. INSTALLING THE C350ap Block

Remove the protective film on the copper base first.

Place the C350ap block on the CPU and tighten the thumb-screws by hand.







FINAL STEP. POWER ON



Please check the following:

- Make sure the block is seated properly on the CPU.
- Always perform a leak test before turning on the system.
- Use paper towels under fittings and joints to avoid damage.
- Make sure all hardware has been tested before starting your water loop.



Let the pump run for multiple hours. Tilting the system can help to release air bubbles.